



TECHNICAL, ENGINEERING AND CONSTRUCTION

PO Box 127 - Jackson, Alabama 36545
Phone: 251-246-9838 Fax: 251-246-7799

SERVICES, INC.
www.tec-services.net

Thermal Imaging Services

Thermographic Report March 2011

Report Date: 04/01/11

MCC Location: MCC26-244	Mill Area: Frontside
Equipment No: 03210-190-07502	Severity: Severe
Description: Primary Screen Number 2	

• 3/09/2011 • 9:27:36 AM



	Ref.	Rect2
Emiss.	0.95	0.95
Avg		180.6 °F
Min		111.5 °F
Max	141.5 °F	238.2 °F
Delta		96.7 °F

Problem	Poor connection left phase line side breaker. T>200F
Recommended remedial action	Clean wire, inspect for damage, re-torque
Inspector	Thomas "Jeff" Motes, Jr., PE
Corrective action taken	
Repaired by	